

### 5.3 THETIS-Med Action Taken

- Codes**

Code	Description
0	No action taken
10	Rectified
15	To be rectified at next port
16	To be rectified within 14 days
17	To be rectified before departure
19	Safety management audit by administration before departure
21	Corrective action taken on the ISM system by the Company is required within 3 months
26	Competent security authority informed
46	To be rectified at agreed repair port
47	As in the agreed class condition
48	As in the agreed flag State condition
49	As in the agreed rectification action plan
55	Flag State Administration consulted
65	Operations stopped
80	Temporary substitution
81	Temporary repair carried out
95	Letter of warning issued
96	Letter of warning withdrawn
99	Master instructed to ...

- Tick Boxes Action Taken**

- Ground for detention
- MARPOL investigation of contravention of discharge provision
- Vessel expelled on security grounds
- Vessel expelled on other grounds
- Inspection suspended
- Dismissed on AFS grounds
- Overriding factor

- Reporting Action Taken**

- Recognized Organization informed
- Flag State informed
- Next port of call informed
- Other authority informed
- ILO informed
- Union representative informed
- Coastal state informed
- Ship owner organization informed